

Simple PID Controlled Dancer Un-winder Setup

This application note will describe the basic set up and programming required for a simple dancer controlled un-winder. This system must also work in reverse as a rewinder.



Machine Data

Core Diameter:	6 inches
Full Roll Diameter:	18 inches
Web width:	12 inches
Tension:	1pli

This method of control does have some limitations since it is not closed loop (i.e. it does not have a true inner current loop) and therefore the torque producing current is calculated based on measured (and entered) motor parameters. In essence, this means that the ability to control motor torque is limited to approximately a 5:1 range with reasonable accuracy. The useable speed range should also be kept in the range of 6 to 60 Hz (180 to 1800rpm on a 4-pole motor) with a typical build up ratio of no more than approximately 4:1. For best results, the motor should be geared in such that at core and maximum line speed the motor runs at rated speed. In general, materials with lower tensile strength such as tissues, lights foils & films should be avoided with this implementation

The drive will be set up to use analog input #2 for the dancer feedback. Note that the voltage across the dancer potentiometer is such that if it drops, the feedback voltage will increase causing the unwind to rotate counterclockwise in order to "pull" the dancer back to center (or set-point) position. A digital set point will be used for dancer position. This set up applies to the Commander SK, Commander GP20 and the Unidrive SP. The terminal strip connections shown are for the Unidrive SP. Block diagrams are taken from <u>CTSoft</u>.



Parameter	Setting	Notes
7.31	50%	Pid setpoint
7.15	0	This disconnects analog input #2, it will be used strictly for the PID
14.03	7.31	This will be the PID set point since its units are 0 to 100%
14.04	7.02	This is the PID dancer feedback
14.08	1	This enables the PID
14.09	1.11	This is an optional PID enable; it is tied to the "drive on" parameter. It keeps the PID integrator reset when the drive is disabled.
14.14	-20.0	This parameter limits the maximum reverse speed of the motor. It should be set based on the application requirements / limitations.
14.16	1.36	This directs the output of the PID to a standard speed register.
14.10	1.000	These are the PID loop tuning parameters. They are set
14.11	0.500	"analytically" per the application. <u>See PID Tuning notes page 6</u>
14.12	0.000	

Note: Register #7.31, used as the PID set point and the PID gains #14.10, #14.11 and #14.12 can be "mapped" to menu 0 in the Commander SK since the "extended" menu's are not accessible from the drive keypad. This is not necessary in the Commander GP20 and the Unidrive SP.

Example mapping:

Parameter	Setting	Parameter	Setting
71	7.31	61	50%
72	14.10	62	1.000
73	14.11	63	0.500
74	14.12	64	0.000

For additional information on mapping parameters, see $\underline{\text{CTAN272}}$ or a Video Tutorial $\underline{\text{CTVI101}}$

In this type application, the motor base speed will be selected based on the maximum line speed and the core diameter. From the machine data above the relationship between motor rpm and line speed in feet per minute is:

FPM = RPM x Pi x core diameter (ft) = RPM x 3.14×0.5 (6 in core diameter) = RPM x 1.57

The motor horsepower will be determined by this RPM, the web tension and the gear ratio if there is a gear box involved.

To keep things simple, we will assume a line speed of 1000 FPM, the motor RPM at this line speed would be 636 RPM. The maximum torque required will be 12 Lbs times the radius at full roll which is .75 FT. The required motor torque would then be 9 Ft-Lbs. If a standard 4 pole (1750 rpm) motor were to be used, the motor horsepower would be:

$$Hp = \frac{Torque \ x \ Speed}{5250} = \frac{9 \ x \ 1750}{5250} = 3 \ HP$$

A three horsepower motor may be cutting it too close in this example due to losses (windage , friction and possibly a slightly higher material tension requirement) so we may need to go up to the next integral horsepower , being 5Hp. Since at 1000FPM the motor rpm is only 636 we are throwing out almost two thirds of the motor horsepower. The addition of a gearbox is probably the best solution in this case. Let's see what happens with a 4: 1 gear box and a 1 Hp motor as opposed to a 5Hp motor directly driving the load. Assuming the gear box is 80 % efficient, the torque available on the output shaft would be:

 $T(out) = \frac{5250 \text{ X Hp}}{(\text{Motor Base Speed / Gear Ratio})} = \frac{(5250 \text{ x 1})}{(1750 / 4)} = 12 \text{ Ft-Lbs}$

With an efficiency of 80%, this would give us a useable torque of $0.8 \times 12 = 9.6$ Ft-Lbs between the speed range of say 65 to 650 RPM (output of gear box). Above the 650 RPM we would be in "field weakening" range which would result in a reduction in available torque but since this is a un-winder / re-winder the torque required at the higher speeds will be less anyway.

The equation for motor torque above base speed is:

$$T = \frac{Motor rated torque @ base speed}{(\% Motor Speed / 100\%)^2}$$

In this example, at core the motor would be running at ~**2547 rpm** (at 1000 fpm with the 4:1 gear box). Therefore the available motor torque would be:

CIAN525.000 VI.I	CTAN325.doc	V1.1
------------------	-------------	------

 $T(at Core speed) = \underline{3 \text{ ft-lbs (at base speed)}}_{(2547 / 1800)^2} = 1.49 \text{ ft-lbs}$

The output shaft of the gear box would have 4 times this amount; therefore **4.8 ft-lbs** (assuming 80% efficient gear box) would be available at the output shaft of the gear box.

The required motor torque to produce the material tension at core is:

T(core torque) = Web Tension X core radius = 12 lbs X (3'' / 12'') = 3 ft- lbs

The required motor torque to produce the material tension at full roll is:

T(full roll torque) = Web Tension X full roll radius = 12 lbs X (9" / 12") = 9 ft- lbs

The graph below will show the approximate motor torque vs. the load torque at various points. The required torque for constant tension is within the available motor torque so a 1 Hp motor should be OK to use.



Additional Programming Notes

As with any application, the drive should be set up and tuned as well as possible **BEFORE** trying to set up the PID loop. For this set up, the drive should be set up for open loop vector control (or better yet, RFC mode if the drive is either an SP or GP20) and a rotating auto tune performed. This will provide the best torque / current control allowing for good dynamic control with **minimal** acceleration / deceleration times. **A dynamic braking resistor is highly recommended especially for larger rolls.** Since the system operates in the extended speed range (above base speed) the maximum frequency setting should be determined based on the equation below:

Max Frequency = <u>Core speed (rpm) X 1.05 X 60 (Hz)</u> = <u>2547 X 1.05 X 60</u> = **89.1 Hz** Motor Base Speed 1800

Application Note on RFC Control Mode -- <u>CTAN296</u>

PID tuning

Using different values of these two gains, you can tune the response of the PID controller to suit the system.

If the system is "Hunting" by overshooting and undershooting, the system is said to be Under Damped.

If the system takes a long time to reach the setpoint, then the system is Over Damped.

The ideal is to have the system critically damped (see diagram below). As each system is different, trial and error using the Proportional and Integral gains to tune the system to a critically damped state is required.



<u>CTScope</u> (click on CTScope to download program) is an ideal tool to use for tuning the PID loop.

Questions: Ask the author??

Steve Zaleski Email: mailto:steve.zaleski@emerson.com

Tel: 800-367-8067