Winmate VESA Bracket Mounting Kit

(For S-Series HMI:
- **W10ID3S-PCH1**   • **W10ID3S-PCH1-PoE**
- **W10FA3S-PCH2AC-PoE**   •**W10FA3S-PCH2-PoE**)

Mechanical Drawing:

How to use Winmate VESA Bracket Mounting Kit ?

1

Screw VESA bracket to the fixture (ex. wall) with four M4 x 5 mm flathead screws.

2

Place the device on the VESA bracket.

NOTE:
Please notice that both hooks on bracket should lock the notches on the back cover of the device.

3

Secure the device from the bottom with one M3 x 4 mm flathead screw.