



world leaders in the art of linear measurement

SI7500

Loading and Saving Settings and Parts

Application Note
502861
Issue 1

▶ Plug a USB flash memory stick into the SI7500's USB port. If loading an existing Settings or Part file onto the SI7500, ensure it is mounted onto the memory stick's root directory.

▶ Turn on the unit and enter the setup menu.

▶ Select the Supervisor screen and enter the supervisor password.

▶ Press Finish twice to exit the Setup menu.

▶ Re-enter the Supervisor screen in the Setup menu.

▶ Select the Supervisor password field and press the softkey below the "Load.." or "Save.." option.

▶ Select the desired data type to save or load by pressing the softkey below the displayed options.

▶ Follow the on-screen prompts to finalise the data transfer.

▶ Done! Press "OK" to exit to the setup menu.

