




IMPORTANT NOTES


IAA Series minimum power supply is 14 VDC for Output load <1500 Ohms. All grounds are connected together and pass through. Power and instrument cable shield connections should be grounded on one end, either at the power and instrument side, or the IAA side, to avoid potential ground loops.


Sensor cable shield connections should be grounded on one end, either the sensor side or the IAA sensor input side, to avoid potential ground loops.


RoHS Compliant

DIMENSIONS inches [mm]









MALE DB9 POWER SIDE	
PIN #	WIRING CODE
1	N/C
2–7	GROUND/SHIELD
8	OUTPUT SIGNAL
9	POWER SUPPLY

FEMALE DB9 SENSOR SIDE	
PIN #	WIRING CODE
1	+ EXCITATION
2	+ SIGNAL
3	– SIGNAL
4	- EXCITATION/SHIELD ¹

¹ For 6 wire sensors, connect +SENSE to +EXCITATION and -SENSE to -EXCITATION.

Drawing Number: FI1392

FUTEK reserves the right to modify its design and specifications without notice. Please visit http://www.futek.com/salesterms for complete terms and conditions.

10 Thomas, Irvine, CA 92618 USA

Tel: (949) 465-0900 Fax: (949) 465-0905











No.1 Bukit Batok Street 22 #01-01 Singapore 659592

SCIGATE AUTOMATION (S) PTE LTD



Fax: (65) 6562 0588

Tel: (65) 6561 0488

Email: sales@scigate.com.sg